Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: MASTON 34-27 #2H

Field Name: BANKS Well File #: 27814

Date Incident:7/12/2014Time Incident:17:14Facility ID Number:County:MCKENZIETwp:153Rng:98Sec:34Qtr:

Location Description:

Submitted By: Jason Percle Received By:

Contact Person: Jason Percle

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:3 MileDistance Nearest Water Well:3 Mile

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil

Brine 35 Barrels 35 Barrels 35 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/1/2016 Clean Up Concluded: 7/13/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

Liquids were contained and cleaned up from surrounding areas. Contaminated soil under rig mats will be cleaned up after mats are moved.

Action Taken or Planned:

Corrective actions include removing hole from tank after transferring fluids and cap all hoses.

Wastes Disposal Location: Newalta disposal

Agencies Involved:

Updates

Date: 7/14/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause during apparent drilling activities, remained on location according to the report. NDIC retains oversight.